

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
239 Blackberry Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2024
245 Blackberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2022
268 Blackberry Dr	C	N	P	Installed after lead ban	N	Field inspection only	Y	2020
302 Blackberry Dr	P	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
320 Blackberry Dr	P	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
325 Blackberry Dr	P	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
330 Blackberry Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2020
211 Cranberry Ct	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
213 Cranberry Ct	C	N	C	Installed after lead ban	N	Installed after lead ban	N	
215 Cranberry Ct	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
117 Dan St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
133 Dan St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
144 Dan St	C	N	C	Installation record	N	Previous eval	Y	2019
147 Dan St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
127 E First St	C	N	C	Installation record	N	Field inspection only	Y	2024
130 E First St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2024
133 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
206 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
212 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
219 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
236 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
245 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
251 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
375 E First St	C	N	C	Installation record	N	Field inspection only	Y	2024
409 E First St	C	N	C	Installation record	N	Field inspection only	y	2020
415 E First St	C	N	C	Installation record	N	Previous eval	Y	2018
417 E First St	C	N	P	Installation record	N	Previous eval	Y	2018
425 E First St	C	N	C	Installation record	N	Previous eval	Y	2018
446 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
449 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
450 E First St	C	N	C	Installation record	N	Field inspection only	Y	2023
2 E Second St	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
4 E Second St								
207 East Ave	C	N	C	Installation record	N	Field inspection only	Y	2023
222 East Ave	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
227 East Ave	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
229 East Ave	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
280 East Ave	C	N	C	Installation record	N	Previous eval	Y	2022
300 East Ave	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
135 Mowtown Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2023
203 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
205 Mulberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
206 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
207 Mulberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
212 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
216 Mulberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
217 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
220 Mulberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
300 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
307 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
320 Mulberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
325 Mulberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
340 Mulberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
347 Mulberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
360 Mulberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
365 Mulberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
119 N Depot St	P	N	C	Installed after lead ban	Y	Field inspection only	Y	2024
235 N Depot St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2019
546 N Depot St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2020
546 N Depot St	C	N	C	Installation record	N	Field inspection only	Y	2024
121 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2021
133 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2024
227 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2024
235 N Harmon St	C	N	C	Installation record	N	Previous eval	Y	2018
240 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2018
308 N Harmon St	C	N	C	Installation record	N	Previous eval	Y	2018
311 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2018
326 N Harmon St	C	N						
331 N Harmon St	C	N	C	Installation record	N	Field inspection only	Y	2024
103 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
109 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
117 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
207 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
215 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
219 N Lawson St	C	N	C	Installation record	N	Previous eval	Y	2021
225 N Lawson St	C	N	C	Installation record	N	Field inspection only	Y	2023
238 N Lyndon St	C	N	C	Installation record	N	Field inspection only	Y	2024
325 N Lyndon St	C	N	C	Installation record	N	Field inspection only	Y	2024

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
331 N Lyndon St	C	N	C	Installation record	N	Field inspection only	Y	2022
425 N Lyndon St	P	N	C	Installed after lead ban	N	Field inspection only	Y	2024
511 N Lyndon St	C	N	C	Installation record	N	Field inspection only	Y	2024
134 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
226 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
312 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
316 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
318 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
324 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2024
329 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
330 N Mill St	C	N	C	Installation record	N	Previous eval	Y	2017
332 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
406 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
407 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
429 N Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
617 Pheasant Run	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
703 Pheasant Run	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
717 Pheasant Run	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
736 Pheasant Run	C	N	P	Installed after lead ban	N	Field inspection only	Y	2024
803 Pheasant Run	C	N	P	Installed after lead ban	N	Field inspection only	Y	2024
812 Pheasant Run	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
520 Red Tail Loop	C	N	P	Installed after lead ban	N	Field inspection only	Y	2024
525 Red Tail Loop	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
113 Russ St	C	N	C	Installed after lead ban	N	Installed after lead ban	N	
116 Russ St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2019
117 Russ St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
132 Russ St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
133 Russ St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
146 Russ St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
147 Russ St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
104 S Mill St	C	N	C	Installed after lead ban	Y	Field inspection only	Y	2023
117 S Mill St	C	N	C	Installation record	N	Field inspection only	Y	2023
216 School St	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
N3594 State Hwy 57	C	N	C	Installation record	N	Field inspection only	Y	2024
306 Strawberry Dr	C	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N	
311 Strawberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
326 Strawberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
335 Strawberry Dr	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
348 Strawberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
364 Strawberry Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2023
370 Strawberry Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2023
375 Strawberry Dr	C	N	C	Installed after lead ban	N	Field inspection only	Y	2019
390 Strawberry Dr	P	N	P	Installed after lead ban	N	Field inspection only	Y	2023
395 Strawberry Dr	C	N	P	Installed after lead ban	N	Field inspection only	Y	2019
108 W First St	C	N	C	Installation record	N	Previous eval	Y	2021
117 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
120 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
125 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
133 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
136 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
142 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
145 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
204 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
209 W First St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
212 W First St	C	N	C	Installation record	N	Previous eval	Y	2017
215 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
224 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
227 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
232 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
235 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
305 W First St	C	N	G	Installation record	N	Field inspection only	Y	2023
308 W First St	C	N	C	Installation record	N	Field inspection only	Y	2024
317 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
323 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
329 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
337 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
348 W First St	C	N	C	Installed after lead ban	Y	Field inspection only	Y	2019
405 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
417 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
420 W First St	C	N	C	Installation record	N	Previous eval	Y	2018
430 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
433 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
507 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
508 W First St	C	N	C	Installation record	N	Previous eval	Y	2021
518 W First St	C	N	C	Installation record	N	Previous eval	Y	2021
521 W First St	C	N	G	Installation record	N	Field inspection only	Y	2023
524 W First St	C	N	P	Installation record	N	Field inspection only	Y	2023

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
535 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
604 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
605 W First St	C	N	C	Installation record	N	Previous eval	Y	2018
607 W First St	C	N	C	Installation record	N	Previous eval	Y	2021
622 W First St	P	N	C	Installation record	N	Field inspection only	Y	2023
645 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
671 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
695 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
711 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
715 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
718 W First St	C	N	C	Installed after lead ban	Y	Field inspection only	Y	2024
741 W First St	C	N	C	Installation record	N	Previous eval	Y	2018
819 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
827 W First St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2023
833 W First St	C	N	C	Installation record	N	Previous eval	Y	2018
1018 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
1102 W First St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2024
1108 W First St	C	N	C	Installation record	N	Field inspection only	Y	2023
1200 W First St	P	N	C	Installed after lead ban	N	Field inspection only	Y	2023
706 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
709 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
716 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
722 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
812 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
815 W Fourth St	C	N	C	Installation record	N	Field inspection only	Y	2023
605 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
608 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
615 W Second St	C	N	C	Installation record	N	Previous eval	Y	2022
621 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
628 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2024
633 W Second St	C	N	C	Installation record	N	Previous eval	Y	2018
705 W Second St	C	N	C	Installation record	N	Previous eval	Y	2018
708 W Second St	C	N	C	Installation record	N	Previous eval	Y	2022
715 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
717 W Second St	C	N	C	Installation record	N	Previous eval	Y	2019
718 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
720 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
730 W Second St	C	N	C	Installation record	N	Previous eval	Y	2020

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE
805 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
810 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2024
817 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2024
822 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2023
827 W Second St	C	N	C	Installation record	N	Field inspection only	Y	2024
828 W Second St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2020
515 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
521 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
522 W Third St	C	N	C	Installation record	N	Previous eval	Y	2022
538 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
612 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2024
615 W Third St	C	N	G	Installation record	N	Field inspection only	Y	2023
618 W Third St	C	N	C	Installation record	N	Previous eval	Y	2019
621 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2024
636 W Third St	C	N	C	Installed after lead ban	N	Field inspection only	Y	2022
641 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
710 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
717 W Third St	C	N	UNK-NOLG	Installation record	N	Field inspection only	Y	2023
718 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
814 W Third St	C	N	C	Installation record	N	Field inspection only	Y	2023
819 W Third St	C	N	C	Installation record	N	Previous eval	Y	2022
824 W Third St	C	N	C	Installation record	N	Previous eval	Y	2022
826 W Third St	C	N	C	Installation record	N	Previous eval	Y	2022